
## Preliminary Hand-Held Air Monitoring Locations | ITC Deer Park Tank Fire

## Reading Date

3/29/2019 2:00:00 AM to 3/29/2019 3:00:00 AM



## Recent Benzene Detections

Location Category	Reading Date	Concentration
Division B	3/29/2019 02:56:14	0.250 ppn
	3/29/2019 02:40:59	0.190 ppn
	3/29/2019 02:38:44	0.330 ppn
	3/29/2019 02:37:22	0.090 ppn
	3/29/2019 02:19:47	0.220 ppn
	3/29/2019 02:16:55	0.430 ppn
	3/29/2019 02:13:13	0.940 ppr
	3/29/2019 02:09:51	0.600 ppr
	3/29/2019 02:05:47	0.180 ppr
	3/29/2019 02:04:51	0.530 ppr
Division E	3/29/2019 02:58:42	1.450 ppr
	3/29/2019 02:47:23	3.500 ppr
	3/29/2019 02:29:51	0.570 ppr
	3/29/2019 02:28:08	0.490 ppr
	3/29/2019 02:26:21	0.300 ppr
	3/29/2019 02:25:03	1.200 ppr
	3/29/2019 02:19:00	0.110 ppr
	3/29/2019 02:15:31	2.475 ppr
	3/29/2019 02:13:02	0.260 ppr
	3/29/2019 02:09:29	0.260 ppr
	3/29/2019 02:06:04	0.350 ppr
	3/29/2019 02:00:59	1.075 ppr
Industrial Area	3/29/2019 02:37:19	0.450 ppr
	3/29/2019 02:33:33	0.175 ppr
	3/29/2019 02:29:13	0.675 ppr
	3/29/2019 02:24:50	0.025 ppn

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only